



FILE: EAL MOT POT RC5
DRAWN BY: FOTIOS A. ANAGNOSTOU
DATE: 19 - 02 - 2012

NOTES:

1. OPTIONAL RESET CIRCUIT. IT SHOULD BE USED WHEN "+5V" SUPPLY POWER-UP SLOPE IS TOO SLOW.
2. "SW1" IS USED EITHER FOR REMOTE CONTROL ADDRESS SET-UP OR FOR MANUAL "MUTE" FUNCTION.
3. PRE - PROGRAMMED INPUT TO CONNECT A SIMILAR SWITCH LIKE "SW1" FOR MANUAL "STBY" FUNCTION.
4. READY OUTPUTS TO DRIVE ONE "MUTE" AND ONE "STBY / POWER ON" RELAY. BOTH WITH 5VDC COIL.
5. IF POTENTIOMETER AND CONTROL PCBs ARE NOT SPLITTED, "CON2" AND "CON4" ARE OMITTED. SOLDER TWO WIRE PIECES IN THEIR PLACE.

6. ALL RESISTORS 0.25W UNLESS NOTED